

General Environmental Incident Summary

Incident: 82 **Date/Time Notice:** 10/1/2001 1600 **DEM Incident No:**

Responsible Party: Montana Dakota Utilities Co

Date Incident: 10/1/2001 **Time Incident:** 1300 **Duration:**

County: Burleigh **Twp:** 138 **Rng:** 80 **Sec:** 4 **Qtr:**

Lat: 46.80196 **Long:** -100.78380 **Method:** Derived from TRS

Location Description: 310 North 9th Street, Bismarck.

Submitted By: Andrea Stromberg

Affiliation: MDU

Address:

City:

State:

Zip:

Received By: Curt Erickson

Contact Person: Andrea Stromberg
400 N 4th St
Bismarck, ND 58501

Distance Nearest Occupied Building: 50 Feet

Type of Incident: Transformer Leak

Description of Released Contaminant: Transformer Oil, less than 2 ppm PCBs

Volume Spilled: 40.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: Unknown

Cause of Incident:

Transformer Leak

Risk Evaluation:

None

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Less than 2 cubic feet of oil contaminated soil.

Action Taken or Planned:

Oil ran onto wood chips used for landscaping. Plastic sheeting is under the wood chips which contained the mineral oil. Oil either soaked into the wood chips or is contained on the plastic. Estimated approximately 2 cubic feet of soil is being removed.

Wastes Disposal Location: Bismarck landfill.

Agencies Involved:

